

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9A




FIG. 9B




FIG. 9C

78

EVACUATED - SAFE
EVACUATED - NEED ASSISTANCE
EVACUATING
EVACUATING - NEED ASSISTANCE
UNABLE TO EVACUATE
ADDITIONAL OCCUPANTS

FIG. 9D

80

ALTERNATE EXIT ROUTE
TAKE LEFT OUT OF OFFICE
TURN RIGHT AT END OF HALL
STAIRS ARE ON LEFT
ACKNOWLEDGE

FIG. 9E

82

IN OFFICE
WEST SIDE STAIRS
EAST SIDE STAIRS
SEND MESSAGE
ADDITIONAL OCCUPANTS

FIG. 9F

84

HANDICAPPED
CRITICALLY INJURED
SERIOUSLY INJURED
SLIGHTLY INJURED
SEND MESSAGE
ADDITIONAL OCCUPANTS

FIG. 9G

86

NEED ASSISTANCE
ENTRAPPED
HANDICAPPED
SEND MESSAGE
ADDITIONAL OCCUPANTS

FIG. 9H

88

OCCUPANT 1	
NAME:	-----
ID:	-----
PHONE:	-----
EMERGENCY CONTACT:	-----
DONE	NEXT

FIG. 9I






FIG. 10A

FIG. 10B

FIG. 10C